



नाशिक महानगरपालिका, नाशिक.

संदर्भ :- वाचा :- महाराष्ट्र आग प्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम 2006

- अग्निशमन व आग्निबाणी सेवा -

- अग्निप्रतिबंधक दाखला - (शैक्षणिक - फार्मसी) -

महाराष्ट्र आग प्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम 2006 नुसार (13) 1

दाखला देणेत येतो की मे. मुंबई एज्युकेशन ट्रस्ट, मुंबई. यांना त्यांची जागा स.नं. 1071/2, आडगांव शिवार, नाशिक. या ठिकाणी बांधलेल्या मे. भुजबळ नॉलेज सिटी. या इमारतीला शैक्षणिक (फार्मसी) या व्यावसायासाठी खालील निम्नलिखित अटी-शर्तीच्या अधिन राहून अग्निप्रतिबंधक दाखला देणेत येत आहे.

-अटीशर्ती -

- 1) सदर दाखला हा फक्त मनपाने मंजूर केलेल्या नकाशावरहुकूम बांधकामासाठी दिलेला आहे. मंजूर कामाव्यतिरिक्त वाढीव बांधकाम व सामाजिक अंतरातील बांधकाम तसेच वापरात बदल केलेला असल्यास अशा अनधिकृत बदल झालेल्या इमारतीच्या भागास सदर दाखला लागू होणार नाही.
- 2) दाखला घेतलेनंतर सदर इमारतीच्या बांधकामात वा वापरात बदल करण्यात आल्यास वा वाढीव बांधकाम केल्यास असा बदल मनपा नगररचना खात्याकडून मंजूर करून घ्यावा लागेल तसेच केलेल्या बदलानुसार अग्निप्रतिबंधक व अग्निविमोचक उपाययोजनांमध्ये नियमानुसार फेरबदल करणे दाखलाधारकावर बंधनकारक राहिल.
- 3) तळघर (बेसमेंट) चा वापर मनपा विकास नियंत्रण नियमावलीनुसार अनुज्ञेय वापरांसाठीच करता येईल. अन्य वापरासाठी सदरचा दाखला लागू होणार नाही.
- 4) ज्या जागेसाठी अग्निप्रतिबंधक दाखला दिलेला आहे त्या ठिकाणी असलेली अग्निप्रतिबंधक व अग्निविमोचक उपाययोजना, उपकरणे, बाहेर पडण्याचे मार्ग, पाण्याचा साठा, आपत्कालीन मार्ग इ. नेहमी सुस्थितीत ठेवणेची जबाबदारी महाराष्ट्र आगप्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम २००६ नुसार मालक / भोगवटादार / दाखलाधारकाची असून त्याबाबत खात्री करून घेणेकामी वर्षातून किमान एक किंवा दोन वेळा अचानक भेटी देवून तपासणी करणेचे अधिकार राखून ठेवलेले आहेत.
- 5) महाराष्ट्र आगप्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम २००६ मधील कलम ३ नुसार सदर ठिकाणी आवश्यक अग्निविमोचक व अग्निप्रतिबंधक उपाययोजना केलेली आहे.
- 6) सुचित केलेनुसार योग्य ती उपाययोजना केलेली नसल्यास अथवा केलेली उपाययोजना वापरण्यास योग्य सुस्थितीत ठेवलेली नाही असे निदर्शनास आल्यास अग्निशामक दलाने दिलेल्या मुदतीत सदर उपाययोजना सुस्थितीत दाखलाधारकावर बंधनकारक राहिल. तसे न केल्यास सदर दाखलाधारकांकडून नियमानुसार दंड वसूल करणेत येईल किंवा महाराष्ट्र आगप्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम २००६ मधील कलम ८, ३६ व ३८ नुसार कारवाई करणेत येईल.
- 7) अस्तित्वात आलेल्या अग्निप्रतिबंधक, अग्निविमोचक उपकरणे व यंत्रसामुग्रीच्या वापराबाबत दाखलाधारक व सदर ठिकाणी काम करणारे कर्मचारी यांना प्रशिक्षण असणे आवश्यक आहे.
- 8) महाराष्ट्र आगप्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम, २००६ मधील कलम ३ (३) नुसार आगप्रतिबंधक व जीवसुरक्षा उपाययोजना दुरुस्त व कार्यक्षम असलेबाबतचे विहित नमुन्यातील प्रमाणपत्र ('बी' फॉर्म) लायसन्स प्राप्त अभिकरणाकडून प्राप्त करून अग्निशामक विभागाकडे वर्षातून दोन वेळा जानेवारी व जुलै महिन्यामध्ये सादर करावे लागेल.

उपरोक्त अटीचा भंग झालेचे निदर्शनास आल्यास सदरचा दाखला कोणतीही पुर्वसुचना न देता रद्द करणेत येईल.

नाशिक. दिनांक : 08/03/2018

वार्षिक फी

बुक नं. 5312

पास नं. 63

र.रु. 7,040/-

दि. 03/03/2018



मुख्य अग्निशमन अधिकारी
नाशिक महानगरपालिका
प्राधिकृत अधिकारी यांची सही
पदनाम व शिक्का

मुख्य अग्निशमन अधिकारी
नाशिक महानगरपालिका


मुख्य अग्निशमन अधिकारी
नाशिक महानगरपालिका

दाखला एकदा घेतलेवर नुतनीकरण करणेची आवश्यकता नाही.

मात्र दरवर्षी वार्षिक फी भरणा करावा लागेल.

तथापि जानेवारी व जुलै महिन्यामध्ये लायसन्स प्राप्त अभिकरणाकडून फॉर्म "बी" प्राप्त

करून सादर केलेबाबतच्या नोंदी करून घेणे बंधनकारक राहिल.

अ.नं.	वर्ष	महिना	वार्षिक फी भरलेचा तपशिल बुक नं./पा.नं. दिनांक	तपासणी केलेबाबत अनुज्ञाप्रीधारक अभिकर्ता यांचे नांव व फॉर्म "B" यांचा दाखला दिनांक	सही
१)	२०१८	जाने. १ जुलै २०१८	—	"अजिंक्य फायर सर्विस" जाने २०१८ ते जुलै २०१८ फॉर्म B. दि २१/७/२०१८	 ३१/७/१८ मुख्य अभियंता कार्यालय नाशिक महानगरपालिका

"बी" फॉर्मची नोंद घेतली



नाशिक महानगरपालिका, नाशिक

एक खिडकी टोकन योजना

अग्निशामक दल ना हरकत दाखला

मिळणेसाठी करावयाचा अर्ज

प्रमुख अग्निशमन अधिकारी

नाशिक महानगरपालिका

अर्जदार मुंबई एज्युकेशनल ट्रस्ट, मुंबई (फार्मसी बिल्डींग) वय.....
दुकानाचे नाव सं. नं. १०७१/२, लायसेन्स नं.....
दुकानाचा पत्ता ग्रामीण पोलीस कार्यालय रोजरी,
राहण्याचा पत्ता आडगाव, नाशिक- ४२२००३

महाशय,

विनंती अर्ज की, मी..... चा व्यवसाय वरील ठिकाणी
करीत आहे. या धंद्यासाठी मला..... चौ. फुट जागेच्या क्षेत्रफळाचा वापर
करायचा आहे. मजकडे एकावेळी..... मालाचा साठा राहिल,
मी सदर जागेमध्ये खालील प्रमाणे अग्निप्रतिबंधक उपाय योजना केलेली आहे.


- १) होय
- २)
- ३)

वरीलपैकी सर्व अग्निनिर्वाणके रिफील केलेली आहेत. तसेच सर्व साहित्य सुस्थितीत व वापरण्यास योग्य आहेत.

तरी महानगरपालिका नियमाप्रमाणे मला सन..... साठी महानगरपालिका लायसेन्स
मिळणेस विनंती आहे. त्यासाठी नियमाप्रमाणे होणारी योग्य ती लायसेन्स फी मी भरावयास तयार आहे. याबाबतच्या
नियमाचे व शर्तीचे पालन करीन.

माझ्या माहितीनुसार वर लिहिलेला मजकूर खरा असून योग्य आहे. अर्जातील माहिती चुकीची अगर खोटी
ठरल्यास मला दिलेले लायसेन्स रद्द होणेस पात्र राहिल.

दिनांक : २८/०१/२०१९



अर्जदाराची सही

अर्जासोबत जोडावयाचे कागदपत्र :

- ०१) गॉपअॅक्ट लागूने

Tax Invoice


(ORIGINAL FOR RECIPIENT)

AJINKYA FIRE PROTECTION SERVICES
 RAUNAK PARK, TIDKE COLONY
 NEAR MICO CIRCLE
 TRIMBAK ROAD
 NASHIK
 GSTIN/UIN: 27ACNPK0371P1Z3
 State Name: Maharashtra, Code: 27
 E-Mail: ajinkyafire@yahoo.com
 Buyer

Mumbai Educational Trust
 Bhujbal Knowledge City
 Adgaon, Nashik
 GSTIN/UIN : 27AAATM0985G1ZH
 State Name : Maharashtra, Code : 27

Invoice No. **18** Dated **30-Apr-2019**
 Delivery Note Mode/Terms of Payment
 Supplier's Ref. Other Reference(s)
18
 Buyer's Order No. Dated
 Despatch Document No. Delivery Note Date
 Despatched through Destination
 Terms of Delivery

SI No	Description of Services	HSN/SAC	GST Rate	Quantity	Rate per	Amount
1	Inspection & Servicing of Fire Fighting Equipments (Servicing for the Month of March-2019)	995469	18%	1 LOT	15,000.00 LOT	15,000.00
	Output CGST					1,350.00
	Output SGST					1,350.00
	Total			1 LOT		17,700.00

Rest as per work of fire fighting equipments completed satisfactory

 (Ashwin P.)

Amount Chargeable (in words) **Indian Rupees Seventeen Thousand Seven Hundred Only**


HSN/SAC	Taxable Value	Central Tax Rate	Central Tax Amount	State Tax Rate	State Tax Amount	Total Tax Amount
995469	15,000.00	9%	1,350.00	9%	1,350.00	2,700.00
Total	15,000.00		1,350.00		1,350.00	2,700.00

Tax Amount (in words) **Indian Rupees Two Thousand Seven Hundred Only**

Company's Bank Details
 Bank Name: Kotak Mahindra Bank Ltd.
 A/c No.: 605011002904
 Branch & IFS Code: Khutwad Nagar, Nashik, KKBK0001912
 for AJINKYA FIRE PROTECTION SERVICES



Declaration: I declare that this invoice shows the actual price of the goods described and that all particulars are true and correct.

30/04/2019


SUBJECT TO NASHIK JURISDICTION
 This is a Computer Generated Invoice

MET Fire Hose Box Report

Sr.No	H.R. box NO	Area	Door condition	Lock key	No.Of Hose	Servicing Date: MARCH 2019				
						No.of Branch Pipe	CAP	Rubber bidding	Glass	Remark
1	1	Near Pump house	✓	✓	2	1	✓	✓	✓	OK
2	2	Pharmacy back side	✓	✓	2	1	✓	✓	✓	OK
3	3	Near canteen	✓	✓	2	1	✓	✓	✓	OK
4	4	Back side canteen	✓	✓	2	1	✓	✓	✓	OK
5	5	Near canteen lawns	✓	✓	2	1	✓	✓	✓	OK
6	6	Back side polytechnic	✓	✓	2	1	✓	✓	✓	OK
7	7	Back side new W.shop	✓	✓	2	1	✓	✓	✓	OK
8	8	Near Workshop	✓	✓	2	1	✓	✓	✓	OK
9	9	Near Workshop	✓	✓	2	1	✓	✓	✓	OK
10	10	Near Workshop	✓	✓	2	1	✓	✓	✓	OK
11	11	Back side institute	✓	✓	2	1	✓	✓	✓	OK
12	12	Back side institute	✓	✓	2	1	✓	✓	✓	OK
13	13	Front Off Core Building	✓	✓	2	1	✓	✓	✓	OK
14	14	Front Off Core Building	✓	✓	2	1	✓	✓	✓	OK
15	15	Back side Sec.Gate-1	✓	✓	2	1	✓	✓	✓	OK
16	16	Back side Sec Gate-1	✓	✓	2	1	✓	✓	✓	OK
17	17	Canteen Ground floor	✓	✓	2	1	✓	✓	✓	OK
18	18	Canteen First floor	✓	✓	2	1	✓	✓	✓	OK
19	19	Canteen Second floor	✓	✓	2	1	✓	✓	✓	OK
20	20	Polytechnic Ground Floor	✓	✓	2	1	✓	✓	✓	OK
21	21	Polytechnic First Floor	✓	✓	2	1	✓	✓	✓	OK
22	22	Polytechnic second floor	✓	✓	2	1	✓	✓	✓	OK
23	23	Polytechnic third floor	✓	✓	2	1	✓	✓	✓	OK
24	24	Polytechnic fourth floor	✓	✓	2	1	✓	✓	✓	OK
25	25	Polytechnic fifth floor	✓	✓	2	1	✓	✓	✓	OK
26	26	Institute eng Ground floor	✓	✓	2	1	✓	✓	✓	OK
27	27	Institute eng first floor	✓	✓	2	1	✓	✓	✓	OK
28	28	Institute eng second floor	✓	✓	2	1	✓	✓	✓	OK
29	29	Institute eng Third floor	✓	✓	2	1	✓	✓	✓	OK
30	30	Institute eng Fourth floor	✓	✓	2	1	✓	✓	✓	OK
31	31	Institute eng fifth floor	✓	✓	2	1	✓	✓	✓	OK
32	32	New W/S Ground floor	✓	✓	2	1	✓	✓	✓	OK
33	33	New W/S First floor	✓	✓	2	1	✓	✓	✓	OK
34	34	New W/S Second floor	✓	✓	2	1	✓	✓	✓	OK
35	35	New W/S third floor	✓	✓	2	1	✓	✓	✓	OK
36	36	New W/S fourth floor	✓	✓	2	1	✓	✓	✓	OK
37	37	New W/S fifth floor	✓	✓	2	1	✓	✓	✓	OK
38	38	Pharmacy ground floor	✓	✓	2	1	✓	✓	✓	OK
39	39	Pharmacy 1st floor	✓	✓	2	1	✓	✓	✓	OK
40	40	Pharmacy 2nd floor	✓	✓	2	1	✓	✓	✓	OK
41	41	Pharmacy 3rd floor	✓	✓	2	1	✓	✓	✓	OK

Refer Points
38,39,40,41
above

श्रीमद्गणेशाय नमः
Bhambhakar
(Sukalal. S. S.)
श्री. S.



श्री. S. S.
श्री. S. S.

श्री. S. S.
श्री. S. S.

MET Pump House Report

No	Pump / HP	Love Joy Coupling	Rubber spider	Gland Packing	Gresing	Servicing Date: MARCH 2019		Remark
						Aliengment	Electrical	
1	Jockey 10HP	✓	✓	✓	✓	✓	✓	OK
2	Main 60HP	✓	✓	✓	✓	✓	✓	OK
3	Spare 60HP	✓	✓	✓	✓	✓	✓	OK

No	Valve Type	Handle	Gland Packing	Spindle	Gasket	Gresing	Remark
1	Sluice valve(jockey)	✓	✓	✓	✓	✓	Ok
2	Sluice valve(Main)	✓	✓	✓	✓	✓	Ok
3	Sluice valve(Spare)	✓	✓	✓	✓	✓	Ok
4	B F valve(main)	✓	✓	✓	✓	✓	Ok
5	B F valve(main)	✓	✓	✓	✓	✓	Ok
6	B F valve(Spare)	✓	✓	✓	✓	✓	Ok
7	B F valve(Water inlet tan)	✓	✓	✓	✓	✓	Ok

Outside area Sluice & B.F valves

No	Valve Type	Handle	Gland Packing	Spindle	Gasket	Greasing	Remark	Area
1	Sluice valve	✓	✓	✓	✓	✓	OK	Near fire pump house
2	Sluice valve	✓	✓	✓	✓	✓	OK	Near fire pump house
3	Sluice valve	✓	✓	✓	✓	✓	OK	Back side pharmacy
4	Sluice valve	✓	✓	✓	✓	✓	OK	Near workshop
5	Sluice valve	✓	✓	✓	✓	✓	OK	Back side instituta
6	B.F valve	✓	✓	✓	✓	✓	OK	Canteen riser
7	B.F valve	✓	✓	✓	✓	✓	OK	Polytechnic riser
8	B.F valve	✓	✓	✓	✓	✓	OK	Instituta riser
9	B.F valve	✓	✓	✓	✓	✓	OK	New workshop riser



दीर्घ यत्नोऽन अस्तान् काले.

Handwritten signature
11/6/2019

Bhandare
(Subkate's 4)
07/5

Handwritten signature
11/6/2019

MET Fire Hose Reel Report

Sr.No	H.R. NO	Area	Servicing Date: MARCH 2019				Remark
			Nozzle	Rubber Pipe	Hose Clamp	Oiling greasing	
1	1	Canteen ground Floor	✓	✓	✓	✓	OK
2	2	Canteen first Floor	✓	✓	✓	✓	OK
3	3	Canteen second Floor	✓	✓	✓	✓	OK
4	4	Polytechnic ground flr.	✓	✓	✓	✓	OK
5	5	Polytechnic first floor	✓	✓	✓	✓	OK
6	6	Polytechnic second floor	✓	✓	✓	✓	OK
7	7	Polytechnic third floor	✓	✓	✓	✓	OK
8	8	Polytechnic fourth floor	✓	✓	✓	✓	OK
9	9	Polytechnic fifth floor	✓	✓	✓	✓	OK
10	10	Institute eng ground floor	✓	✓	✓	✓	OK
11	11	Institute eng first floor	✓	✓	✓	✓	OK
12	12	Institute eng second floor	✓	✓	✓	✓	OK
13	13	Institute eng third floor	✓	✓	✓	✓	OK
14	14	Institute eng fourth floor	✓	✓	✓	✓	OK
15	15	Institute eng fifth floor	✓	✓	✓	✓	OK
16	16	New W/S ground floor	✓	✓	✓	✓	OK
17	17	New W/S first floor	✓	✓	✓	✓	OK
18	18	New W/S second floor	✓	✓	✓	✓	OK
19	19	New W/S third floor	✓	✓	✓	✓	OK
20	20	New W/S Fourth floor	✓	✓	✓	✓	OK
21	21	New W/S fifth floor	✓	✓	✓	✓	OK
22	22	Pharmacy ground floor	✓	✓	✓	✓	OK
23	23	Pharmacy 1st floor	✓	✓	✓	✓	OK
24	24	Pharmacy 2nd floor	✓	✓	✓	✓	OK
25	25	Pharmacy 3rd floor	✓	✓	✓	✓	OK



वीरम पुत्रो काम उद्योग कामे उद्ये

Handwritten signature
MET/Pu.uber.

Sheendax
(Suzakel. S. U)
27-5.

Handwritten signature
Shivan P. /

MET HYDRANT VALVE REPORT

Servicing Date: MARCH 2019

Sr.No	H.Y.D. NO	Area	Spares					Oiling & Greasing	Remark
			Lug	Outer Washer	Spindle Washer	Operating Wheel	Spindal		
1	1	Near Pump house	✓	✓	✓	✓	✓	OK	
2	2	Pharmacy back side	✓	✓	✓	✓	✓	OK	
3	3	Near canteen lawns	✓	✓	✓	✓	✓	OK	
4	4	Back side Canteen	✓	✓	✓	✓	✓	OK	
5	5	Near canteen lawns	✓	✓	✓	✓	✓	OK	
6	6	back side polytechnic	✓	✓	✓	✓	✓	OK	
7	7	Back side new w shop	✓	✓	✓	✓	✓	OK	
8	8	Near workshop	✓	✓	✓	✓	✓	OK	
9	9	Near Workshop	✓	✓	✓	✓	✓	OK	
10	10	Near workshop	✓	✓	✓	✓	✓	OK	
11	11	BackSide institute	✓	✓	✓	✓	✓	OK	
12	12	Back Side institute	✓	✓	✓	✓	✓	OK	
13	13	Front off core Building	✓	✓	✓	✓	✓	OK	
14	14	Front off core Building	✓	✓	✓	✓	✓	OK	
15	15	Back side sec.Gate-1	✓	✓	✓	✓	✓	OK	
16	16	Back side sec.Gate-1	✓	✓	✓	✓	✓	OK	
17	17	Canteen Ground Floor	✓	✓	✓	✓	✓	OK	
18	18	Canteen First floor	✓	✓	✓	✓	✓	OK	
19	19	Canteen second Floor	✓	✓	✓	✓	✓	OK	
20	20	Polytechnic ground fir.	✓	✓	✓	✓	✓	OK	
21	21	Polytechnic First Floor	✓	✓	✓	✓	✓	OK	
22	22	Polytechnic Second Floor	✓	✓	✓	✓	✓	OK	
23	23	Polytechnic Third floor	✓	✓	✓	✓	✓	OK	
24	24	Polytechnic Fourth Floor	✓	✓	✓	✓	✓	OK	
25	25	Polytechnic fifth floor	✓	✓	✓	✓	✓	OK	
26	26	Institute eng Ground floor	✓	✓	✓	✓	✓	OK	
27	27	Institute eng First floor	✓	✓	✓	✓	✓	OK	
28	28	Institute eng Second floor	✓	✓	✓	✓	✓	OK	
29	29	Institute eng third floor	✓	✓	✓	✓	✓	OK	
30	30	Institute eng fourth floor	✓	✓	✓	✓	✓	OK	
31	31	Institute eng fifth floor	✓	✓	✓	✓	✓	OK	
32	32	New W/S Ground floor	✓	✓	✓	✓	✓	OK	
33	33	New W/S First floor	✓	✓	✓	✓	✓	OK	
34	34	New W/S Second floor	✓	✓	✓	✓	✓	OK	
35	35	New W/S Third floor	✓	✓	✓	✓	✓	OK	
36	36	New W/S fourth floor	✓	✓	✓	✓	✓	OK	
37	37	New W/S fifth floor	✓	✓	✓	✓	✓	OK	
38	38	Pharmacy ground floor	✓	✓	✓	✓	✓	OK	
39	39	Pharmacy 1st floor	✓	✓	✓	✓	✓	OK	
40	40	Pharmacy 2nd floor	✓	✓	✓	✓	✓	OK	
41	41	Pharmacy 3rd floor	✓	✓	✓	✓	✓	OK	



वार्डम यंत्रणे वरुन वरुतान मरुतु वरुतु

Handwritten signature
M.B. P. number

Rhindekar
(Sukalal. e. u.)
M.S.

Handwritten signature
- [illegible]

MET Fire Hose Reel Report

r.No	H.R. NO	Area	Servicing Date: MARCH 2019					Remark
			Nozzle	Rubber Pipe	Hose Clamp	Oiling greasing		
1	1	Canteen ground Floor	√	√	√	√	OK	
2	2	Canteen first Floor	√	√	√	√	OK	
3	3	Canteen second Floor	√	√	√	√	OK	
4	4	Polytechnic ground fir.	√	√	√	√	OK	
5	5	Polytechnic first floor	√	√	√	√	OK	
6	6	Polytechnic second floor	√	√	√	√	OK	
7	7	Polytechnic third floor	√	√	√	√	OK	
8	8	Polytechnic fourth floor	√	√	√	√	OK	
9	9	Polytechnic fifth floor	√	√	√	√	OK	
10	10	Institute eng ground floor	√	√	√	√	OK	
11	11	Institute eng first floor	√	√	√	√	OK	
12	12	Institute eng second floor	√	√	√	√	OK	
13	13	Institute eng third floor	√	√	√	√	OK	
14	14	Institute eng fourth floor	√	√	√	√	OK	
15	15	Institute eng fifth floor	√	√	√	√	OK	
16	16	New W/S ground floor	√	√	√	√	OK	
17	17	New W/S first floor	√	√	√	√	OK	
18	18	New W/S second floor	√	√	√	√	OK	
19	19	New W/S third floor	√	√	√	√	OK	
20	20	New W/S Fourth floor	√	√	√	√	OK	
21	21	New W/S fifth floor	√	√	√	√	OK	
22	22	Pharmacy ground floor	√	√	√	√	OK	
23	23	Pharmacy 1st floor	√	√	√	√	OK	
24	24	Pharmacy 2nd floor	√	√	√	√	OK	
25	25	Pharmacy 3rd floor	√	√	√	√	OK	



कीमत पुनो काम करवाना काम करे करे

Handwritten signature
MET/PU/101

Shundekar
(Sukalal. S. U.)
M.S.

Handwritten signature
10/10/2019



नाशिक महानगरपालिका, नाशिक.

संदर्भ :- वाचा :- महाराष्ट्र आग प्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम 2006

- अग्निशमन व आग्निबाणी सेवा -

- अग्निप्रतिबंधक दाखला - (शैक्षणिक - फार्मसी) -

महाराष्ट्र आग प्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम 2006 नुसार (13) 1

दाखला देणेत येतो की मे. मुंबई एज्युकेशन ट्रस्ट, मुंबई. यांना त्यांची जागा स.नं. 1071/2, आडगांव शिवार, नाशिक. या ठिकाणी बांधलेल्या मे. भुजबळ नॉलेज सिटी. या इमारतीला शैक्षणिक (फार्मसी) या व्यावसायासाठी खालील निम्नलिखित अटी-शर्तीच्या अधिन राहून अग्निप्रतिबंधक दाखला देणेत येत आहे.

-अटीशर्ती -

- 1) सदर दाखला हा फक्त मनपाचे मंजूर केलेल्या नकाशावरहुकूम बांधकामासाठी दिलेला आहे. मंजूर कामाव्यतिरिक्त वाढीव बांधकाम व सामाजिक अंतरातील बांधकाम तसेच वापरात बदल केलेला असल्यास अशा अन्नधिकृत बदल झालेल्या इमारतीच्या भागास सदर दाखला लागू होणार नाही.
- 2) दाखला घेतलेनंतर सदर इमारतीच्या बांधकामात वा वापरात बदल करण्यात आल्यास वा वाढीव बांधकाम केल्यास असा बदल मनपा नगररचना खात्याकडून मंजूर करून घ्यावा लागेल तसेच केलेल्या बदलानुसार अग्निप्रतिबंधक व अग्निविमोचक उपाययोजनांमध्ये नियमानुसार फेरबदल करणे दाखलाधारकावर बंधनकारक राहिल.
- 3) तळधर (बेसमेंट) चा वापर मनपा विकास नियंत्रण नियमावलीनुसार अनुज्ञेय वापरासाठीच करता येईल. अन्य वापरासाठी सदरचा दाखला लागू होणार नाही.
- 4) ज्या जागेसाठी अग्निप्रतिबंधक दाखला दिलेला आहे त्या ठिकाणी असलेली अग्निप्रतिबंधक व अग्निविमोचक उपाययोजना, उपकरणे, बाहेर पडण्याचे मार्ग, पाण्याचा साठा, आपत्कालीन मार्ग इ. नेहमी सुस्थितीत ठेवणेची जबाबदारी महाराष्ट्र आगप्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम 2006 नुसार मालक / भोगवटादार / दाखलाधारकाची असून त्याबाबत खात्री करून घेणेकामी वर्षातून किमान एक किंवा दोन वेळा अचानक शेटी देवून तपासणी करणेचे अधिकार राखून ठेवलेले आहेत.
- 5) महाराष्ट्र आगप्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम 2006 मधील कलम 2 नुसार सदर ठिकाणी आवश्यक अग्निविमोचक व अग्निप्रतिबंधक उपाययोजना केलेली आहे.
- 6) सुचित केलेनुसार योग्य ती उपाययोजना केलेली नसल्यास अथवा केलेली उपाययोजना वापरण्यास योग्य सुस्थितीत ठेवलेली नाही असे निदर्शनास आल्यास अग्निशामक दलाने दिलेल्या मुदतीत सदर उपाययोजना सुस्थितीत दाखलाधारकावर बंधनकारक राहिल. तसे न केल्यास सदर दाखलाधारकांकडून नियमानुसार दंड वसूल करणेत येईल किंवा महाराष्ट्र आगप्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम 2006 मधील कलम 7, 36 व 37 नुसार कारवाई करणेत येईल.
- 7) अस्तित्वात आलेल्या अग्निप्रतिबंधक, अग्निविमोचक उपकरणे व यंत्रसामुग्रीच्या वापराबाबत दाखलाधारक व सदर ठिकाणी काम करणारे कर्मचारी यांना प्रशिक्षण असणे आवश्यक आहे.
- 8) महाराष्ट्र आगप्रतिबंधक व जीवसुरक्षा उपाययोजना अधिनियम 2006 मधील कलम 3 (3) नुसार आगप्रतिबंधक व जीवसुरक्षा उपाययोजना दुरुस्त व कार्यक्षम असलेबाबतचे विहित नमुन्यातील प्रमाणपत्र ("बी" फॉर्म) लायसन्स प्राप्त अभिकरणाकडून प्राप्त करून अग्निशामक विभागाकडे वर्षातून दोन वेळा जाणेवारी व जुलै महिन्यामध्ये सादर करावे लागेल.

उपरोक्त अटीचा भंग झालेचे निदर्शनास आल्यास सदरचा दाखला कोणतीही पुर्वसूचना न देता रद्द करणेत येईल.

नाशिक. दिनांक : 03/03/2018

वार्षिक फी

वुक नं. 5312

पास नं. 63

र.रु. 7,040/-

दि. 03/03/2018




मुख्य कार्यकारी अधिकारी
नाशिक महानगरपालिका
प्राधिकृत अधिकारी यांची सही
पदनाम व शिक्का

मुसलधारण आपरथक नाही.
याच "बी" फॉर्म वरवरवीं दोनदा

अ.नं.	वर्ष	महिना	वार्षिक फी भरलेचा तपशिल बुक नं./पा.नं. दिनांक	तपासणी केलेबाबत अनुज्ञाप्रीधारक अभिकर्ता यांचे नांव व फॉर्म "B" यांचा दाखला दिनांक	सही
9)	209L	जानेवारी जून 209L फॉर्म "B" वर सही	—	तपासणी केलेबाबत दिनांक: 02/07/2019	89/0196 मुख्य अभियंता नाशिक महानगरपालिका
८)	209L	जानेवारी जून 209L फॉर्म "B" वर सही	अज्ञानसुरमा निधी बुक EUCLEPA 49 वक्रकम. - 9923491 दि. 97/01/209L वार्षिक फी बुक EUCLEPA 49 वक्रकम. - 34201 दि. 97/01/209L	अज्ञानसुरमा निधी फॉर्म "B" वर दि. 21/1/209L "बी" फॉर्मची नोंद घेतली	मुख्य अभियंता नाशिक महानगरपालिका सह "B" फॉर्म भरण्याची सोप्या सादर कराया. मुख्य अभियंता नाशिक महानगरपालिका

MET The Pump House Report

Mar-18

No	Pump / HP	Love Joy Coupling	Rubber spider	Gland Packing	Greasing	Allignment	Electrical	Remark
1	Jockey 10HP	✓	✓	refilled	✓	✓	✓	OK
2	Main 60HP	✓	✓	refilled	✓	✓	✓	OK
3	Spare 60HP	✓	✓	✓	✓	✓	✓	Over load relay damage, not operated pump

No	Valve Type	Handle	Gland Packing	Spindle	Gasket	Greasing	Remark
1	Sluice valve(jockey)	✓	✓	✓	✓	✓	Ok
2	Sluice valve(Main)	✓	✓	✓	✓	✓	Ok
3	Sluice valve(Spare)	✓	✓	✓	✓	✓	Ok
4	B.F valve(main)	✓	✓	✓	✓	✓	Ok
5	B.F valve(main)	✓	✓	✓	✓	✓	Ok
6	B.F valve(Spare)	✓	✓	✓	✓	✓	Ok
7	B.F valve(Water inlet tan)	✓	✓	✓	✓	✓	Ok

Outside area Sluice & B.F valves								
No	Valve Type	Handle	Gland Packing	Spindle	Gasket	Greasing	Remark	Area
1	Sluice valve	✓	✓	✓	✓	✓	OK	Near fire pump house
2	Sluice valve	✓	✓	✓	✓	✓	OK	Near fire pump house
3	Sluice valve	✓	✓	✓	✓	✓	OK	Back side pharmacy
4	Sluice valve	✓	✓	✓	✓	✓	OK	Near workshop
5	B.F valve	✓	✓	✓	✓	✓	OK	Back side institute
6	B.F valve	✓	✓	✓	✓	✓	OK	Canteen riser
7	B.F valve	✓	✓	✓	✓	✓	OK	Polytechnic riser
8	B.F valve	✓	✓	✓	✓	✓	OK	Institute riser
9	B.F valve	✓	✓	✓	✓	✓	OK	New workshop riser

Note: Fire Hydrant System Under ground Pipe Line Leakage findout & repair ok.

*Pravin
Chambers
Plumber*

*Shindeen
(Sulawesi)
m.s*



(Signature)
(Signature)

Mar-18

Sr. No.	Ext.No.	Area	Type	Kg	Operatig Valve	Discharg eHose	Safety Pin	Hose Bracket	Refilling Date	Due Date	Remark
1	1	Fire pump house	ABC	5	✓	✓	✓	✓	08.08.2017	08.08.2019	OK
2	2	Core building EPR	ABC	5	✓	✓	✓	✓	08.08.2017	08.08.2019	OK
3	3	Core building Server Room (ground)	ABC	5	✓	✓	✓	✓			OK
4	4	Core building (GR floor)	ABC	5	✓	✓	✓	✓	23.09.2017	23.09.2019	OK
5	5	Core building (GR floor)	ABC	5					26.05.2017	26.05.2019	OK
6	6	Core building (1st floor)	ABC	5	✓	✓	✓	✓	26.05.2017	26.05.2019	OK
7	7	Core building (1st floor)	ABC	5	✓	✓	✓	✓	04.04.2018	04.04.2020	OK
8	8	Pharmacy building (GR floor)	ABC	5	✓	✓	✓	✓	09.12.2017	09.12.2019	OK
9	9	Pharmacy building (GR floor)	ABC	5					09.02.2017	09.02.2019	OK
10	10	Pharmacy building (1st floor)	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
11	11	Pharmacy building (1st floor)	ABC	5	✓	✓	✓	✓	04.01.2018	04.01.2020	OK
12	12	Pharmacy building (2nd floor)	ABC	5	✓	✓	✓	✓	09.12.2017	09.12.2019	OK
13	13	Pharmacy building (2nd floor)	ABC	5	✓	✓	✓	✓	09.12.2017	09.12.2019	OK
14	14	MBA building (GR floor)	ABC	5	✓	✓	✓	✓	28.07.2016	28.07.2018	OK
15	15	MBA building (GR floor)	ABC	5	✓	✓	✓	✓	28.07.2017	28.07.2018	OK
16	16	MBA building	ABC	5	✓	✓	✓	✓	08.08.2016	08.08.2019	OK
17	17	MBA building	ABC	5	✓	✓	✓	✓	04.04.2018	04.04.2020	OK
18	18	Canteen building (GR floor)	ABC	5	✓	✓	✓	✓	11.08.2017	11.08.2019	OK
19	19	Canteen building (1st floor)	ABC	5	✓	✓	✓	✓	03.01.2017	03.01.2019	OK
20	20	Canteen building (2nd floor)	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
21	21	Canteen building (kitchen)	ABC	5	✓	✓	✓	✓	08.08.2017	08.08.2019	OK
22	22	Eng. Institute 5th floor	ABC	5	✓	✓	✓	✓	03.01.2017	03.01.2019	OK
23	23	Eng. Institute 4th floor	ABC	5	✓	✓	✓	✓	26.05.2017	26.05.2019	OK
24	24	Eng. Institute 3rd floor	ABC	5	✓	✓	✓	✓	08.08.2017	08.08.2019	OK
25	25	Eng. Institute 2nd floor	ABC	5	✓	✓	✓	✓	08.08.2017	08.08.2019	OK
26	26	Eng. Institute 1st floor	ABC	5	✓	✓	✓	✓	08.08.2017	08.08.2019	OK
27	27	Eng. Institute (GR floor)	ABC	5	✓	✓	✓	✓	08.08.2017	08.08.2019	OK
28	28	Polytechnic 5th floor	ABC	5	✓	✓	✓	✓	08.08.2017	08.08.2019	OK
29	29	Polytechnic 4th floor	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

MET Fire Hose Box Report

Mar-18

Sl. No.	H.R. box NO	Area	Door condition	Lock key	No. Of Hose	No. of Branch Pipe	Rubber bidding	Glass	Remark
1	1	Near Pump house	✓	✓	2	1	✓	✓	
2	2	Pharmacy back side	✓	✓	2	1	✓	✓	2 Hose pipe leakage
3	3	Near canteen	✓	✓	2	1	✓	✓	1 Hose pipe leakage, n hose pipe lug missing
4	4	Back side canteen	✓	✓	2	1	✓	✓	OK
5	5	Near canteen lawns	✓	✓	2	1	✓	✓	OK
6	6	Back side polytechnic	✓	✓	2	1	✓	✓	Glass break n hose pipe leakage, n hose pipe lug missing
7	7	Back side new W.shop	✓	✓	2	1	✓	✓	Glass break changed 1 Hose pipe leakage
8	8	Near Workshop	✓	✓	2	1	✓	✓	2 Hose pipe leakage
9	9	Near Workshop	✓	✓	3	1	✓	✓	1 Hose pipe leakage
10	10	near Workshop	✓	✓	2	1	✓	✓	Hose box bottom slit broken
11	11	Back side institute	✓	✓	2	1	✓	✓	OK
12	12	Back side institute	✓	✓	2	1	✓	✓	OK
13	13	Front Off Core Building	✓	✓	2	1	✓	✓	OK
14	14	Front Off Core Building	✓	✓	2	1	✓	✓	OK
15	15	Back side Sec Gate-1	✓	✓	2	1	✓	✓	OK
16	16	Back side Sec Gate-1	✓	✓	2	1	✓	✓	OK
17	17	Canteen Ground floor	✓	✓	2	1	✓	✓	key glass changed OK
18	18	Canteen First floor	✓	✓	2	1	✓	✓	OK
19	19	Canteen Second floor	✓	✓	2	1	✓	✓	OK
20	20	Polytechnic Ground Floor	✓	✓	2	1	✓	✓	OK
21	21	Polytechnic First Floor	✓	✓	2	1	✓	✓	OK
22	22	Polytechnic second floor	✓	✓	2	1	✓	✓	OK
23	23	Polytechnic third floor	✓	✓	2	MISSING	✓	✓	OK
24	24	Polytechnic fourth floor	✓	✓	2	1	✓	✓	OK
25	25	Polytechnic fifth floor	✓	✓	2	1	✓	✓	OK
26	26	Institute eng Ground floor	✓	✓	2	1	✓	✓	OK
27	27	Institute eng first floor	✓	✓	2	1	✓	✓	OK
28	28	Institute eng second floor	✓	✓	2	1	✓	✓	OK
29	29	Institute eng third floor	✓	✓	2	1	✓	✓	OK
30	30	Institute eng Fourth floor	✓	✓	2	1	✓	✓	OK
31	31	Institute eng fifth floor	✓	✓	2	1	✓	✓	OK
32	32	New W/S Ground floor	✓	✓	2	1	✓	✓	OK
33	33	New W/S First floor	✓	✓	2	1	✓	✓	OK
34	34	New W/S Second floor	✓	✓	2	1	✓	✓	OK
35	35	New W/S third floor	✓	✓	2	1	✓	✓	OK
36	36	New W/S fourth floor	✓	✓	2	1	✓	✓	OK
37	37	New W/S fifth floor	✓	✓	2	1	✓	✓	OK

[Signature]
18/3/2018

[Signature]
Inspector (S)

[Signature]
Bhankar Chakraborty

[Signature]
[Illegible]

from [illegible] for garden use

MET HYDRANT VALVE REPORT

Sr.No	H.Y.D. NO	Area	Spares					Mar-18	
			Lug	Outer Washer	Spindle Washer	Operating Wheel	Spindal	Oiling & Greasing	Remark
1	1	Near Pump house	✓	✓	✓	✓	✓	✓	OK
2	2	Pharmacy back side	✓	✓	✓	jam (Repairing)	✓	✓	OK
3	3	Near canteen lawns	✓	✓	✓	jam (Repairing)	✓	✓	OK
4	4	Back side Canteen	✓	✓	✓	✓	✓	✓	OK
5	5	Near canteen lawns	✓	✓	✓	✓	✓	✓	OK
6	6	back side polytechnic	✓	✓	✓	✓	✓	✓	OK
7	7	Back side new w.shop	✓	✓	✓	✓	✓	✓	OK
8	8	Near workshop	damage	(Repairing)	✓	✓	✓	✓	OK
9	9	Near Workshop	✓	✓	✓	✓	✓	✓	OK
10	10	Near workshop	✓	✓	✓	✓	✓	✓	OK
11	11	BackSide institute	✓	✓	✓	✓	✓	✓	OK
12	12	Back Side institute	✓	✓	✓	✓	✓	✓	OK
13	13	Front off core Building	✓	✓	✓	✓	✓	✓	OK
14	14	Front off core Building	✓	✓	✓	✓	✓	✓	OK
15	15	Back side sec.Gate-1	✓	✓	✓	✓	✓	✓	OK
16	16	Back side sec.Gate-1	✓	✓	✓	✓	✓	✓	OK
17	17	Canteen Ground Floor	✓	✓	✓	✓	✓	✓	OK
18	18	Canteen First floor	✓	✓	✓	✓	✓	✓	OK
19	19	Canteen second floor	✓	✓	✓	✓	✓	✓	OK
20	20	Polytechnic ground flr.	✓	✓	✓	✓	✓	✓	OK
21	21	Polytechnic First Floor	✓	✓	✓	✓	✓	✓	OK
22	22	Polytechnic Second Floor	✓	✓	✓	✓	✓	✓	OK
23	23	Polytechnic Third floor	✓	✓	✓	✓	✓	✓	OK
24	24	Polytechnic Fourth Floor	✓	✓	✓	✓	✓	✓	OK
25	25	Polytechnic fifth floor	✓	✓	✓	✓	✓	✓	OK
26	26	Institute eng Ground floor	✓	✓	✓	✓	✓	✓	OK
27	27	Institute eng First floor	✓	✓	✓	✓	✓	✓	OK
28	28	Institute eng Second floor	✓	✓	✓	✓	✓	✓	OK
29	29	Institute eng third floor	✓	✓	✓	✓	✓	✓	OK
30	30	Institute eng fourth floor	✓	✓	✓	✓	✓	✓	OK
31	31	Institute eng fifth floor	✓	✓	✓	✓	✓	✓	OK
32	32	New W/S Ground floor	✓	✓	✓	✓	✓	✓	OK
33	33	New W/S First floor	✓	✓	✓	✓	✓	✓	OK
34	34	New W/S Second floor	✓	✓	✓	✓	✓	✓	OK
35	35	New W/S Third floor	✓	✓	✓	✓	✓	✓	OK
36	36	New W/S fourth floor	✓	✓	✓	✓	✓	✓	OK
37	37	New W/S fifth floor	✓	✓	✓	✓	✓	✓	OK

(Kharneer S)



*Shantabai
(Subaltern)
M.S.*

*Am.
P.*

MET Fire Hose Reel Report

Sr.No	H.R. NO	Area	Nozzle	Rubber Pipe	Mar-18		
					Hose Clamp	Oiling greasing	Remark
1	1	Canteen fround Floor	√	√	√	√	OK
2	2	Canteen first Floor	√	√	√	√	OK
3	3	Canteen second Floor	√	√	√	√	OK
4	4	Polytechnic ground flr.	√	√	√	√	OK
5	5	Polytechnic first floor	√	√	√	√	OK
6	6	Polytechnic second floor	√	√	√	√	OK
7	7	Polytechnic third floor	√	√	√	√	OK
8	8	Polytechnic fourth floor	√	√	√	√	OK
9	9	Polytechnic fifth floor	√	√	√	√	OK
10	10	Institute eng ground floor	√	√	√	√	OK
11	11	Institute eng first floor	√	√	√	√	OK
12	12	Institute eng second floor	√	Chnaged	√	√	OK
13	13	Institute eng third floor	√	√	√	√	OK
14	14	Institute eng fourth floor	√	√	√	√	OK
15	15	Institute eng fifth floor	√	√	√	√	OK
16	16	New W/S ground floor	√	√	√	√	OK
17	17	New W/S first floor	√	√	√	√	OK
18	18	New W/S second floor	√	√	√	√	OK
19	19	New W/S third floor	√	√	√	√	OK
20	20	New W/S Fourth floor	√	√	√	√	OK
21	21	New W/S fifth floor	√	√	√	√	OK



*Inspected
(checked) by
Plumber*

*Shantaram
(Gukal: 5-4)
07-5.*

*[Signature]
(Plumber P.)*

MET FIRE EXTINGUISHER SERVICING REPORT

DATE :- MARCH 2017

Sr. No.	Ext. No.	Area	Type	Kg	Operatig Valve	Discharge Hose	Safety Pin	Hose Bracket	Refilling Date	Due Date	Remark
1	1	Fire pump house	ABC	5	✓	✓	✓	✓	09.02.2017	19.01.2019	OK
2	2	Core building EPR	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
3	3	Core building Server Room (ground)	ABC	5	✓	✓	✓	✓	04.08.2015	04.08.2017	OK
4	4	Core building (GR floor)	ABC	5	✓	✓	✓	✓	29.4.2015	29.4.2017	OK
5	5	Core building (1st floor)	ABC	5	✓	✓	✓	✓	07.12.2015	07.12.2017	OK
6	6	Core building (1st floor)	ABC	5	✓	✓	✓	✓	07.12.2015	07.12.2017	OK
7	7	Pharmacy building (GR floor)	ABC	5	✓	✓	✓	✓	03.01.2017	03.01.2019	OK
8	8	Pharmacy building (GR floor)	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
9	9	Pharmacy building (1st floor)	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
10	10	Pharmacy building (2nd floor)	ABC	5	✓	✓	✓	✓	09.20.2017	09.02.2019	OK
11	11	Pharmacy building (2nd floor)	ABC	5	✓	✓	✓	✓	28.07.2016	28.07.2018	OK
12	12	MBA building (GR floor)	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
13	13	MBA building (GR floor)	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
14	14	MBA building	ABC	5	✓	✓	✓	✓	29.04.2015	29.04.2017	OK
15	15	MBA building	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
16	16	Canteen building (GR floor)	ABC	5	✓	✓	✓	✓	03.01.2017	03.01.2019	OK
17	17	Canteen building (1st floor)	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
18	18	Canteen building (2nd floor)	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
19	19	Canteen building (kitchen)	ABC	5	✓	✓	✓	✓	03.01.2017	03.01.2019	OK
20	20	Eng. Institute 5th floor	ABC	5	✓	✓	✓	✓	29.04.2015	29.04.2017	OK
21	21	Eng. Institute 4th floor	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
22	22	Eng. Institute 3rd floor	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
23	23	Eng. Institute 2nd floor	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
24	24	Eng. Institute 1st floor	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
25	25	Eng. Institute (GR floor)	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
26	26	Polytechnic 5th floor	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
27	27	Polytechnic 4th floor	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
28	28	Polytechnic 3rd floor	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
29	29	Polytechnic 2nd floor	ABC	5	✓	✓	✓	✓	07.12.2015	07.12.2017	OK
30	30	Polytechnic 1st floor	ABC	5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
31	31	Polytechnic (GR floor)	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
32	32	Polytechnic basement	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
33	33	Workshop	DCP	5	✓	✓	✓	✓	04.08.2015	04.08.2017	OK
34	34	Workshop	DCP	5	✓	✓	✓	✓	04.08.2015	04.08.2017	OK
35	35	Workshop	DCP	5	✓	✓	✓	✓	04.08.2015	04.08.2017	OK
36	36	Workshop	ABC	5	✓	✓	✓	✓	07.12.2015	07.12.2017	OK
37	37	Workshop	ABC	2	✓	✓	✓	✓	22.01.2017	22.01.2019	OK
38	38	New Workshop (GR floor)	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
39	39	New Workshop (Room)	ABC	5	✓	✓	✓	✓	07.12.2015	07.12.2017	OK
40	40	New Workshop (Room)	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
41	41	New Workshop (1st floor)	Co2	4.5	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
42	42	New Workshop (2nd floor)	ABC	5	✓	✓	✓	✓	28.07.2015	28.07.2017	OK
43	43	Sub station	Co2	4.5	✓	✓	✓	✓	04.08.2015	04.08.2017	OK
44	44	Sub station	ABC	5	✓	✓	✓	✓	04.08.2015	04.08.2017	OK
45	45	Sub station	ABC	5	✓	✓	✓	✓	07.12.2015	07.12.2017	OK
46	46	Sub station	ABC	5	✓	✓	✓	✓	28.07.2016	28.07.2018	OK
47	47	Core Building (Envi. Lab)	ABC	2	✓	✓	✓	✓	19.01.2017	19.01.2019	OK
48	48	Security gate no.2	ABC	5	✓	✓	✓	✓	07.12.2015	07.12.2017	OK
49	49	Security gate no.1	ABC	6	✓	✓	✓	✓	09.02.2017	09.02.2019	OK
50	50	Pharmacy building	ABC	1	✓	✓	✓	✓	17.04.2015	17.04.2017	OK
51	51	Pharmacy building	ABC	1	✓	✓	✓	✓	03.01.2017	03.01.2019	OK
52	52	Pharmacy building	ABC	1	✓	✓	✓	✓	03.01.2017	03.01.2019	OK
53	53	Pharmacy building	ABC	1	✓	✓	✓	✓	17.04.2015	17.04.2017	OK
54	54	Pharmacy building	ABC	1	✓	✓	✓	✓	17.04.2015	17.04.2017	OK
55	55	Pharmacy building	ABC	1	✓	✓	✓	✓	17.04.2015	17.04.2017	OK
56	56	Pharmacy building	ABC	1	✓	✓	✓	✓	17.04.2015	17.04.2017	OK
57	57	Pharmacy building	ABC	1	✓	✓	✓	✓	17.04.2015	17.04.2017	OK

Mary
Met. Sec. Plumber

Bhandekar
(Sukal. S. K.)
M.S.



Bhatnagar

MET HYDRANT VALVE REPORT

Servicing Date: MARCH 2017

Sr.No	H.Y.D. NO.	Area	Spares					Oiling & Greasing	Remark
			Lug	Outer Washer	Spindo Washer	Operating Wheel	Spindal		
1	1	Near Pump house	✓	✓	✓	✓	✓	OK	
2	2	Pharmacy back side	✓	✓	✓	✓	✓	OK	
3	3	Near canteen lawns	✓	✓	✓	✓	✓	OK	
4	4	Back side Canteen	✓	✓	✓	✓	✓	OK	
5	5	Near canteen lawns	✓	✓	✓	✓	✓	OK	
6	6	back side polytechnic	✓	✓	✓	✓	✓	OK	
7	7	Back side new w/shop	✓	✓	✓	✓	✓	OK	
8	8	Near workshop	✓	✓	✓	✓	✓	OK	
9	9	Near Workshop	✓	✓	✓	✓	✓	OK	
10	10	Near workshop	✓	✓	✓	✓	✓	OK	
11	11	BackSide institute	✓	✓	✓	✓	✓	OK	
12	12	Back Side institute	✓	✓	✓	✓	✓	OK	
13	13	Front off core Building	✓	✓	✓	✓	✓	OK	
14	14	Front off core Building	✓	✓	✓	✓	✓	OK	
15	15	Back side sec.Gate-1	✓	✓	✓	✓	✓	OK	
16	16	Back side sec.Gate-1	✓	✓	✓	✓	✓	OK	
17	17	Canteen Ground Floor	✓	✓	✓	✓	✓	OK	
18	18	Canteen First floor	✓	✓	✓	✓	✓	OK	
19	19	Canteen second Floor	✓	✓	✓	✓	✓	OK	
20	20	Polytechnic ground flr.	✓	✓	✓	✓	✓	OK	
21	21	Polytechnic First Floor	✓	✓	✓	✓	✓	OK	
22	22	Polytechnic Second Floor	✓	✓	✓	✓	✓	OK	
23	23	Polytechnic Third floor	✓	✓	✓	✓	✓	OK	
24	24	Polytechnic Fourth Floor	✓	✓	✓	✓	✓	OK	
25	25	Polytechnic fifth floor	✓	✓	✓	✓	✓	OK	
26	26	Institute eng Ground floor	✓	✓	✓	✓	✓	OK	
27	27	Institute eng First floor	✓	✓	✓	✓	✓	OK	
28	28	Institute eng Second floor	✓	✓	✓	✓	✓	OK	
29	29	Institute eng third floor	✓	✓	✓	✓	✓	OK	
30	30	Institute eng fourth floor	✓	✓	✓	✓	✓	OK	
31	31	institute eng fifth floor	✓	✓	✓	✓	✓	OK	
32	32	New W/S Ground floor	✓	✓	✓	✓	✓	OK	
33	33	New W/S First floor	✓	✓	✓	✓	✓	OK	
34	34	New W/S Second floor	✓	✓	✓	✓	✓	OK	
35	35	New W/S Third floor	✓	✓	✓	✓	✓	OK	
36	36	New W/S fourth floor	✓	✓	✓	✓	✓	OK	
37	37	New W/S fifth floor	✓	✓	✓	✓	✓	OK	

Mary
Met-Red Plumber

Rhundevar
(Sukelvel.S.G.)
M.S.

AS
M.H. P.



MET The Pump House Report

Servicing Date: MARCH 2017

No	Pump / HP	Love Joy Coupling	Rubber spider	Gland Packing	Greasing	Aliengment	Electrical	Remark
1	Jockey 10HP	√	√	√	√	√	√	pressure switch Auto Not Working
2	Main 60HP	√	√	√	√	√	√	OK
3	Spare 60HP	√	√	√	√	√	√	OK

No	Valve Type	Handle	Gland Packing	Spindle	Gasket	Gresing	Remark
1	Sluice valve(jockey)	√	√	√	√	√	Ok
2	Sluice valve(Main)	√	√	√	√	√	Ok
3	Sluice valve(Spare)	√	√	√	√	√	Ok
4	B.F valve(main)	√	√	√	√	√	Ok
5	B.F valve(main)	√	√	√	√	√	Ok
6	B.F valve(Spare)	√	√	√	√	√	Ok
7	B.F valve(Water inlet tan)	√	√	√	√	√	Ok

Outside area Sluice & B.F valves

No	Valve Type	Handale	Gland Packing	Spindle	Gasket	Greasing	Remar	Area
1	Sluice valve	√	√	√	√	√	OK	Near fire pump house
2	Sluice valve	√	√	√	√	√	OK	Near fire pump house
3	Sluice valve	√	√	√	√	√	OK	Back side pharmacy
4	Sluice valve	√	√	√	√	√	OK	Near workshop
5	Sluice valve	√	√	√	√	√	OK	Back side institute
6	B.F valve	√	√	√	√	√	OK	Canteen riser
7	B.F valve	√	√	√	√	√	OK	Polytechnic riser
8	B.F valve	√	√	√	√	√	OK	Institute riser
9	B.F valve	√	√	√	√	√	OK	New workshop riser

[Signature]

Money
Main B.F. Plumber

Shindekar
(Subed / cet. S. G.)



MET Fire Hose Box Report

Servicing Date: MARCH 2017									
Sr. No	H.R. box NO	Area	Door condition	Lock key	No. Of Hose	No. of Branch Pipe	Rubber bidding	Glass	Remark
1	1	Near Pump house	√	OK	2	1	√	√	OK
2	2	Pharmacy back side	√	√	2	1	√	√	OK
3	3	Near canteen	√	√	2	1	√	√	OK
4	4	Back side canteen	√	√	2	1	√	√	OK
5	5	Near canteen lawns	√	√	1	1	√	√	OK
6	6	Back side polytechnic	√	√	2	1	√	√	OK
7	7	Back side new W. shop	√	√	2	1	√	√	OK
8	8	Near Workshop	√	√	2	1	√	√	Hose box bottom slit broken
9	9	Near Workshop	√	√	2	1	√	√	OK
10	10	Near Workshop	√	√	2	1	√	√	OK
11	11	Back side institute	√	√	2	1	√	√	OK
12	12	Back side institute	√	√	2	1	√	√	OK
13	13	Front Off Core Building	√	√	2	1	√	√	OK
14	14	Front Off Core Building	√	√	2	1	√	√	OK
15	15	Back side Sec. Gate-1	√	√	2	1	√	√	OK
16	16	Back side Sec Gate-1	√	√	2	1	√	√	OK
17	17	Canteen Ground floor	√	√	2	1	√	√	OK
18	18	Canteen First floor	√	√	2	1	√	√	OK
19	19	Canteen Second floor	√	√	2	1	√	√	OK
20	20	Polytechnic Ground Floor	√	√	2	1	√	√	OK
21	21	Polytechnic First Floor	√	√	2	1	√	√	OK
22	22	Polytechnic second floor	√	√	2	1	√	√	OK
23	23	Polytechnic thirc floor	√	√	2	1	√	√	OK
24	24	Polytechnic fourth floor	√	√	2	1	√	√	OK
25	25	Polytechnic fifth floor	√	√	2	1	√	√	OK
26	26	Institute eng Ground floor	√	√	2	1	√	√	OK
27	27	institute eng first floor	√	√	2	1	√	√	OK
28	28	institute eng second floor	√	√	2	1	√	√	OK
29	29	institute eng Third floor	√	√	2	1	√	√	OK
30	30	institute eng Fourth floor	√	√	2	1	√	√	OK
31	31	institute eng fifth floor	√	√	2	1	√	√	OK
32	32	New W/S Ground floor	√	√	2	1	√	√	OK
33	33	New W/S First floor	√	√	2	1	√	√	OK
34	34	New W/S Second floor	√	√	2	1	√	√	OK
35	35	New W/S third floor	√	√	2	1	√	√	OK
36	36	New W/S fourth floor	√	√	2	1	√	√	OK
37	37	New W/S fifth floor	√	√	2	1	√	√	OK

M. S. Bhandekar
 Met. Br. Plumber
 Bhandekar
 (Sulakar S. 49)
 m.c.

A. S.



MET Fire Hose Reel Report

Servicing Date: MARCH 2017

Sr. No	H.R. NO	Area	Nozzle	Rubber Pipe	Hose Clamp	Oiling greasing	Remark
1	1	Canteen ground Floor	√	√	√	√	OK
2	2	Canteen first Floor	√	√	√	√	OK
3	3	Canteen second Floor	√	√	√	√	OK
4	4	Polytechnic ground flr.	√	√	√	√	OK
5	5	Polytechnic first floor	√	√	√	√	OK
6	6	Polytechnic second floor	√	√	√	√	OK
7	7	Polytechnic third floor	√	√	√	√	OK
8	8	Polytechnic fourth floor	√	√	√	√	OK
9	9	Polytechnic fifth floor	√	√	√	√	OK
10	10	Institute eng ground floor	√	√	√	√	OK
11	11	Institute eng first floor	√	√	√	√	OK
12	12	Institute eng second floor	√	√	√	√	OK
13	13	Institute eng third floor	√	√	√	√	OK
14	14	Institute eng fourth floor	√	√	√	√	OK
15	15	Institute eng fifth floor	√	√	√	√	OK
16	16	New W/S ground floor	√	√	√	√	OK
17	17	New W/S first floor	√	√	√	√	OK
18	18	New W/S second floor	√	√	√	√	OK
19	19	New W/S third floor	√	√	√	√	OK
20	20	New W/S Fourth floor	√	√	√	√	OK
21	21	New W/S fifth floor	√	√	√	√	OK

Signature
MET Plumber

Signature



Signature
(Sub. Cat. S.C.)
M.S

FIRE EXTINGUISHER REPORT

Date: Dec 2015

Ext No	Area	Type	Kg	Operating Valve	Discharge Hose	Safety Pin	Hose Bracket	Refilling Date	Due Date	Remark
1	Fire pump house	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
2	Core building	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
3	Core building	ABC	5	✓	✓	✓	✓	04-08-2015	4/8/2017	OK
4	Core building	ABC	5	✓	✓	✓	✓	28-07-2015	28-7-2017	OK
5	Core building	ABC	5	✓	✓	✓	✓	04-08-2015	4/8/2017	OK
6	Core building	ABC	5	✓	✓	✓	✓	28-7-2015	28-7-2017	OK
7	Pharmacy building	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
8	Pharmacy building	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
9	Pharmacy building	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
10	Pharmacy building	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
11	Pharmacy building	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
12	MBA building	ABC	5	✓	✓	✓	✓	13-11-2014	13-11-2015	OK
13	MBA building	ABC	5	✓	✓	✓	✓	25-7-2014	25-7-2015	OK
14	MBA building	ABC	5	✓	✓	✓	✓	28-7-2015	28-7-2017	OK
15	MBA building	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
16	Canteen building	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
17	Canteen building	ABC	5	✓	✓	✓	✓	28-7-2015	28-7-2017	OK
18	Canteen building	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
19	Canteen building	ABC	5	✓	✓	✓	✓	28-7-2015	28-7-2017	OK
20	Institute 4th floor	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
21	Institute 3rd floor	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
22	Institute 2nd floor	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
23	Institute 1st floor	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
24	Institute ground floor	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
25	Polytecnic 4th floor	ABC	5	✓	✓	✓	✓	13-11-2014	13-11-2015	OK
26	Polytecnic 3rd floor	Co2	4.5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
27	Polytecnic 2nd floor	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
28	Polytecnic 1st floor	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
29	Polytecnic ground floor	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
30	Polytecnic basement	ABC	5	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
31	Core building enviro-lab	ABC	2	✓	✓	✓	✓	19-1-2015	19-1-2017	OK
32	Workshop	DCP	5	✓	✓	✓	✓	4/8/2015	4/8/2017	OK
33	Workshop	DCP	5	✓	✓	✓	✓	4/8/2015	4/8/2017	OK
34	Workshop	DCP	5	✓	✓	✓	✓	4/8/2015	4/8/2017	OK
35	New Workshop	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
36	New Workshop	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
37	New Workshop	ABC	5	✓	✓	✓	✓	13-11-2014	13-11-2015	OK
38	New Workshop	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
39	New Workshop	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
40	Sub station	Co2	4.5	✓	✓	✓	✓	04-08-2015	04-08-2017	OK
41	Sub station	ABC	5	✓	✓	✓	✓	13-11-2014	13-11-2015	OK
42	Sub station	ABC	5	✓	✓	✓	✓	19-1-2014	19-1-2016	OK
43	Security gate no 2	ABC	5	✓	✓	✓	✓	13-11-2014	13-11-2015	OK
44	Institute 5th floor	ABC	5	✓	✓	✓	✓	28-07-2015	28-07-2017	OK
45	Workshop	ABC	2	✓	✓	✓	✓	22-1-2015	22-1-2017	OK
46	Sub station	ABC	5	✓	✓	✓	✓	19-1-2014	19-1-2016	OK
47	Workshop	ABC	5	✓	✓	✓	✓	28-7-2015	28-7-2017	OK
48	Farmacy	ABC	5	✓	✓	✓	✓	29-4-2015	29-4-2017	OK
49	Spare	ABC	5	✓	✓	✓	✓	29-4-2015	29-4-2017	OK
50	Polytecnic 5th floor	ABC	5	✓	✓	✓	✓	29-4-2015	29-4-2017	OK
51	Spare	ABC	5	✓	✓	✓	✓	29-4-2015	29-4-2017	OK

[Handwritten signatures and notes at the bottom of the page]

Jan-2016

MET HOSTEL FIRE EXTINGUISHER SERVICING REPORT

Date: Jan 2015

Ext. No	Area	Type	Kg	Oprating Valve	Discharge Hose	Safety Pin	Hose Brak	Refilling Date	Due Date	Remark
1	Ladies Hostel	ABC	5	√	√	√	√	13-11-2014	13-11-2015	Ok
2	Ladies Hostel Canteen	ABC	5	√	√	√	√	04.08.2015	04.08.2017	Ok
3	Ladies Hostel Canteen	ABC	5	√	√	√	√	04.08.2015	04.08.2017	Ok
4	Ladies Hostel Canteen	ABC	5	√	√	√	√	13-11-2014	13-11-2015	Ok
5	Boys Hostel	ABC	5	√	√	√	√	13-11-2014	13-11-2015	Ok
6	Boys Hostel	ABC	5	√	√	√	√	29-4-2015	29-4-2017	Ok
7	Boys Hostel	ABC	5	√	√	√	√	29-4-2015	29-4-2017	Ok
7	Boys Hostel	ABC	5	√	√	√	√	29-4-2015	29-4-2017	Ok
7	Boys Hostel	ABC	5	√	√	√	√	29-4-2015	29-4-2017	Ok
8	Boys Hostel	ABC	5	√	√	√	√	29-4-2015	29-4-2017	Ok
9	Boys Hostel	ABC	5	√	√	√	√	13-11-2014	13-11-2015	Ok
10	Boys Hostel	ABC	5	√	√	√	√	04.08.2015	04.08.2017	Ok
11	Boys Hostel	ABC	5	√	√	√	√	04.08.2015	04.08.2017	Ok
12	Boys Hostel	CO2	4.5	√	√	√	√	04.08.2015	04.08.2017	Ok
13	Boys Hostel	DCP	4.5	√	√	√	√	04.08.2015	04.08.2017	Ok
14	Spare	ABC	4.5	√	√	√	√	04.08.2015	04.08.2017	Empty
15	Spare	ABC	5.5	√	√	√	√	04.08.2015	04.08.2017	Ok

Rhundelex
(SUNIL-S'4)

Khairat
(Khairat-S'4)



As
Incharge

Jan-2016

Hose Reel

Date: Jan 2016

Sr. No	HR No	Location	Nozzle	Rubber Pipe	Hose Clamp	Oiling & Greasing	Remark
1	1	Canteen Ground Floor	✓	✓	✓	✓	Not OK
2	2	Canteen First Floor	✓	✓	✓	✓	OK
3	3	Canteen Second Floor	✓	✓	✓	✓	OK
4	4	Polytechnic Ground Fl.	✓	✓	✓	✓	Not OK
5	5	Polytechnic First Floor	✓	✓	✓	✓	OK
6	6	Polytechnic Second Floor	✓	✓	✓	✓	OK
7	7	Polytechnic Third Floor	✓	✓	✓	✓	OK
8	8	Polytechnic Fourth Floor	✓	✓	✓	✓	OK
9	9	Polytechnic Fifth Floor	✓	✓	✓	✓	OK
10	10	Institute Ground Floor	✓	✓	✓	✓	OK
11	11	Institute First Floor	✓	✓	✓	✓	OK
12	12	Institute Second Floor	✓	✓	✓	✓	OK
13	13	Institute Third Floor	✓	✓	✓	✓	OK
14	14	Institute Fourth Floor	✓	✓	✓	✓	OK
15	15	Institute Fifth Floor	✓	✓	✓	✓	OK
16	16	New W/S Ground Floor	✓	✓	✓	✓	OK
17	17	New W/S First Floor	✓	✓	✓	✓	OK
18	18	New W/S Second Floor	✓	✓	✓	✓	OK
19	19	New W/S Third Floor	✓	✓	✓	✓	OK
20	20	New W/S Fourth Floor	✓	✓	✓	✓	OK
21	21	New W/S Fifth Floor	✓	✓	✓	✓	OK

Shundar
(Sundar S.G.)

Feeble
(Khumsy)



(Alkins P.)

Jan 2016

Hose Box

Servicing Date: Jan 2016

Sr. No	Hose Box No	Area	Door Condition	Lock Key	No. of Hoses	No. of Branch Pipe	No. of Washer	Glass	Remark
1	1	Near pump House	✓	✓	2	1	✓	✓	OK
2	2	Pharmacy Back Side	✓	✓	2	1	✓	✓	OK
3	3	Near Canteen	✓	✓	2	1	✓	X	OK
4	4	Back Side Canteen	✓	✓	2	1	✓	✓	OK
5	5	Near Canteen Lawns	✓	✓	2	1	✓	✓	OK
6	6	Back Side Polytechnic	✓	✓	2	1	✓	✓	OK
7	7	Back Side New W. Shop	✓	✓	2	1	✓	✓	OK
8	8	Near Workshop	✓	✓	2	1	✓	✓	OK
9	9	Near Workshop	✓	✓	2	1	✓	✓	OK
10	10	Near Workshop	✓	✓	2	1	✓	X	OK
11	11	Back Side Institute	✓	✓	2	1	✓	✓	OK
12	12	Back Side Institute	✓	✓	2	1	✓	✓	OK
13	13	Front Off Core Building	✓	✓	2	1	✓	✓	OK
14	14	Front Off Core Building	✓	✓	2	1	✓	✓	OK
15	15	Back Side Sec. Gate-1	✓	✓	2	1	✓	✓	OK
16	16	Back Side Sec. Gate-1	✓	✓	2	1	✓	X	OK
17	17	Canteen Ground Floor	✓	✓	2	1	✓	✓	OK
18	18	Canteen First Floor	✓	✓	2	1	✓	X	OK
19	19	Canteen Second Floor	✓	✓	2	1	✓	✓	OK
20	20	Polytechnic Ground Flr.	✓	✓	✓	✓	✓	✓	OK
21	21	Polytechnic First floor	✓	✓	✓	✓	✓	✓	OK
22	22	Polytechnic Second Floor	✓	✓	✓	✓	✓	✓	OK
23	23	Polytechnic Third Floor	✓	✓	✓	✓	✓	✓	OK
24	24	Polytechnic Fourth Floor	✓	✓	✓	✓	✓	✓	OK
25	25	Polytechnic Fifth floor	✓	✓	✓	✓	✓	✓	OK
26	26	Institute Ground Floor	✓	✓	✓	✓	✓	✓	OK
27	27	Institute First Floor	✓	✓	✓	✓	✓	✓	OK
28	28	Institute Second Floor	✓	✓	✓	✓	✓	✓	OK
29	29	Institute Third Floor	✓	✓	✓	✓	✓	✓	OK
30	30	Institute Fourth Floor	✓	✓	✓	✓	✓	✓	OK
31	31	Institute Fifth Floor	✓	✓	✓	✓	✓	✓	OK
32	32	New W/S Ground Floor	✓	✓	✓	✓	✓	✓	OK
33	33	New W/S First Floor	✓	✓	✓	✓	✓	✓	OK
34	34	New W/S Second Floor	✓	✓	✓	✓	✓	✓	OK
35	35	New W/S Third Floor	✓	✓	✓	✓	✓	✓	OK
36	36	New W/S Fourth Floor	✓	✓	✓	✓	✓	✓	OK
37	37	New W/S Fifth Floor	✓	✓	✓	✓	✓	✓	OK

Shundela
(Sundel-54)

(Khetwar-54)

(Mishra)



Fire Pump House Report								
No	HP	Love joy coupling	Rubber spider	Gland packing	Greasing	Aliengment	Electrical	Remark
1	Jockey	✓	✓	✓	✓	✓	✓	OK
2	Main	✓	✓	✓	✓	✓	✓	OK
3	Spare	✓	✓	✓	✓	✓	✓	OK
								OK
No	Valve Type	Handle	Gland packing	Spindle	Gasket	Greasing		Remark
1	Sluice Valve (Jockey)	✓	✓	✓	✓	✓		OK
2	Sluice Valve (Main)	✓	✓	✓	✓	✓		OK
3	Sluice Valve (Spare)	✓	✓	✓	✓	✓		OK
4	B.F Valve (Jockey)	✓	✓	✓	✓	✓		OK
5	B.F Valve (Main)	✓	✓	✓	✓	✓		OK
6	B.F Valve (Spare)	✓	✓	✓	✓	✓		OK
7	B.F Valve (Water inlet tank)	✓	✓	✓	✓	✓		OK
Outside Area Sluice & B.F Valves								OK
No	Valve Type	Handle	Gland Packing	Spindle	Gasket	Greasing	Remark	Area
1	Sluice Valve	✓	✓	✓	✓	✓	OK	Near fire pump house
2	Sluice Valve	✓	✓	✓	✓	✓	OK	Near fire pump house
3	Sluice Valve	✓	✓	✓	✓	✓	OK	Back side pharmacy
4	Sluice Valve	✓	✓	✓	✓	✓	OK	Near Workshop
5	B.F Valve	✓	✓	✓	✓	✓	OK	Back side post box
6	B.F Valve	✓	✓	✓	✓	✓	OK	Canteen riser
7	B.F Valve	✓	✓	✓	✓	✓	OK	Polytechnic riser
8	B.F Valve	✓	✓	✓	✓	✓	OK	Institute riser
9	B.F Valve	✓	✓	✓	✓	✓	OK	New workshop riser

Shunabekor
(Sukumar S)

(Kumar S)

Resh

7/11/2017

Jan-2016

HYDRANT VALVE'S REPORT

Servicing Date Jan 2016

Sl. No.	(I.Y.) No.	Area	Spares Lug	Outlet Washer	Sheet Washer	Operating Wheel	Spindal	Oiling & Greasing	Remark
1	1	Near pump House	✓	✓	✓	✓	✓	✓	OK
2	2	Pharmacy Back Side	✓	✓	✓	✓	✓	✓	OK
3	3	Near Canteen	✓	✓	✓	✓	✓	✓	OK
4	4	Back Side Canteen	✓	✓	✓	✓	✓	✓	OK
5	5	Near Canteen Lawns	✓	✓	✓	✓	✓	✓	OK
6	6	Back Side Polytechnic	✓	✓	✓	✓	✓	✓	OK
7	7	Back Side New W.Shop	✓	✓	✓	✓	✓	✓	OK
8	8	Near Workshop	✓	✓	✓	✓	✓	✓	OK
9	9	Near Workshop	✓	✓	✓	✓	✓	✓	OK
10	10	Near Workshop	✓	✓	✓	✓	✓	✓	OK
11	11	Back Side Institute	✓	✓	✓	✓	✓	✓	OK
12	12	Back Side Institute	✓	✓	✓	✓	✓	✓	OK
13	13	Front Off Core Building	✓	✓	✓	✓	✓	✓	OK
14	14	Front Off Core Building	✓	✓	✓	✓	✓	✓	OK
15	15	Back Side Sec.Gate-1	✓	✓	✓	✓	✓	✓	OK
16	16	Back Side Sec. Gate-1	✓	✓	✓	✓	✓	✓	OK
17	17	Canteen Ground Floor	✓	✓	✓	✓	✓	✓	OK
18	18	Canteen First Floor	✓	✓	✓	✓	✓	✓	OK
19	19	Canteen Second Floor	✓	✓	✓	✓	✓	✓	OK
20	20	Polytechnic Ground Flr.	✓	✓	✓	✓	✓	✓	OK
21	21	Polytechnic First Floor	✓	✓	✓	✓	✓	✓	OK
22	22	Polytechnic Second Floor	✓	✓	✓	✓	✓	✓	OK
23	23	Polytechnic Third Floor	✓	✓	✓	✓	✓	✓	OK
24	24	Polytechnic Fourth Floor	✓	✓	✓	✓	✓	✓	OK
25	25	Polytechnic Fifth Floor	✓	✓	✓	✓	✓	✓	OK
26	26	Institute Ground Floor	✓	✓	✓	✓	✓	✓	OK
27	27	Institute First Floor	✓	✓	✓	✓	✓	✓	OK
28	28	Institute Second Floor	✓	✓	✓	✓	✓	✓	OK
29	29	Institute Thrd Floor	✓	✓	✓	✓	✓	✓	OK
30	30	Institute Fourth Floor	✓	✓	✓	✓	✓	✓	OK
31	31	Institute Fifth Floor	✓	✓	✓	✓	✓	✓	OK
32	32	New W/S Ground Floor	✓	✓	✓	✓	✓	✓	OK
33	33	New W/S First Floor	✓	✓	✓	✓	✓	✓	OK
34	34	New W/S Second Floor	✓	✓	✓	✓	✓	✓	OK
35	35	New W/S Third Floor	✓	✓	✓	✓	✓	✓	OK
36	36	New W/S Fourth Floor	✓	✓	✓	✓	✓	✓	OK
37	37	New W/S Fifth Floor	✓	✓	✓	✓	✓	✓	OK

Bhandarkar
(Sub-insp)

Inspector
Mumbai City



Inspector
Mumbai City

Fire Pump Hose report

Date- 13/1/2016

No	Type	Rubber Sheet	Dish Washer	Gasket Fitting		Remark
1	Non Return Valve (Jockey)	✓	✓	✓		OK
2	Non Return Valve (Main)	✓	✓	✓		OK
3	Non Return Valve (Spare)		✓	✓		OK
		Auto	Setting	Cable	Electrical Switch	
1	Pressure Switch (Jockey)	✓	Star-6Kg, Stop-7Kg	✓	✓	OK
2	Pressure Switch (Main)	✓	Star-4Kg, Stop-Manual	✓	✓	OK
3	Pressure Switch (Spare)	✓	Star-3Kg, Stop-Manual	✓	✓	OK
		Gauge	Syphon	Valve		
1	Pressure Gauge (Jockey)	✓	✓	✓		OK
2	Pressure Gauge (Main)	✓	✓	✓		OK
3	Pressure Gauge (Spare)	✓	✓	✓		OK

~~Signature~~
(Signature)
13/1/2016

Signature

Signature
(Signature)

Signature
(Signature)

Jan - 2015

FIRE EXTINGUISHER REPORT

No.	Area	Type	Kg	Operating Valve	Discharge Hose	Safety Pin	Hose Bracket	Refilling Date	Due Date	Remark
1	Fire pump house	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
2	Core building	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
3	Core building	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
4	Core building	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
5	Core building	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
6	Core building	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
7	Pharmacy building	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
8	Pharmacy building	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
9	Pharmacy building	ABC	5	✓	✓	✓	Change	19-1-15	19-1-17	OK
10	Pharmacy building	ABC	5	✓	✓	✓	✓	14.11.14	14.11.15	OK
11	Pharmacy building	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
12	MBA building	ABC	5	✓	✓	✓	Change	14.11.14	14.11.15	OK
13	MBA building	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
14	MBA building	ABC	5	Change	✓	✓	Change	19-1-15	19-1-17	OK
15	MBA building	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
16	Canteen building	ABC	5	✓	✓	✓	Change	19-1-15	19-1-17	OK
17	Canteen building	ABC	5	✓	✓	✓	Change	25-7-14	25-7-15	OK
18	Canteen building	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
19	Canteen building	ABC	5	✓	✓	✓	Change	19-1-15	19-1-17	OK
20	Institute 4th floor	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
21	Institute 3rd floor	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
22	Institute 2nd floor	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
23	Institute 1st floor	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
24	Institute ground floor	ABC	5	✓	✓	✓	Change	25-7-14	25-7-15	OK
25	Polytechnic 4th floor	ABC	5	✓	✓	✓	Change	14.11.14	14.11.15	OK
26	Polytechnic 3rd floor	Co2	4.5	✓	✓	✓	✓	19-1-15	19-1-17	OK
27	Polytechnic 2nd floor	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
28	Polytechnic 1st floor	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
29	Polytechnic ground floor	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
30	Workshop	ABC	5	✓	✓	✓	✓	19-1-15	19-1-17	OK
31	Workshop	ABC	2	✓	✓	✓	✓	19-1-15	19-1-17	OK
32	Workshop	DCP	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
33	Workshop	DCP	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
34	New Workshop	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
35	New Workshop	ABC	5	✓	✓	✓	Change	25-7-14	25-7-15	OK
36	New Workshop	ABC	5	Change	✓	✓	✓	25-7-14	25-7-15	OK
37	New Workshop	ABC	5	✓	✓	✓	✓	13-11-14	13-11-15	OK
38	New Workshop	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
39	Sub station	ABC	5	✓	✓	✓	Change	25-7-14	25-7-15	OK
40	Sub station	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
41	Security gate no 2	ABC	5	✓	✓	✓	✓	14.11.14	14.11.15	OK
42	Security gate no 1	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
43	Civil office	ABC	5	✓	✓	✓	✓	25-7-14	25-7-15	OK
44	Core building	ABC	2	✓	✓	✓	✓	22-1-15	22-1-17	OK
45	Workshop	DCP	5	✓	✓	✓	✓	25-7-14	25-7-15	OK

Inspected by Shankar Singh Fire Extinguisher चेक के
 के लिए Refilling करवाया गया है
 मालिक को सूचित किया गया है
 मालिक का नाम Shankar Singh
 (Signature)



Jan. 2015

HYDRANT VALVE'S REPORT										
Sr.No.	H.Y.D. No	Area	Spares					Servicing Date:	Oiling & Greasing	Remark
			Lug	Outer Washer	Spindle Washer	Operating Wheel	Spindel			
1	1	Near pump House	✓	✓	✓	✓	✓	✓	OK	
2	2	Pharmacy Back Side	✓	✓	✓	✓	✓	✓	OK	
3	3	Near Canteen	✓	✓	✓	✓	✓	✓	OK	
4	4	Back Side Canteen	✓	✓	✓	✓	✓	✓	OK	
5	5	Near Canteen Lawns	✓	✓	✓	✓	✓	✓	OK	
6	6	Back Side Polytechnic	✓	Change ✓	✓	✓	✓	✓	OK	
7	7	Back Side New W.Shop	✓	✓	✓	✓	✓	✓	OK	
8	8	Near Workshop	✓	Change ✓	✓	✓	✓	✓	OK	
9	9	Near Workshop	✓	Change ✓	✓	✓	✓	✓	OK	
10	10	Near Workshop	✓	✓	✓	✓	✓	✓	OK	
11	11	Back Side Institute	✓	✓	✓	✓	✓	✓	OK	
12	12	Back Side Institute	✓	✓	✓	✓	✓	✓	OK	
13	13	Front Off Core Building	✓	✓	✓	✓	✓	✓	OK	
14	14	Front Off Core Building	✓	✓	✓	✓	✓	✓	OK	
15	15	Back Side Sec Gate-1	✓	✓	✓	✓	✓	✓	OK	
16	16	Back Side Sec. Gate-1	✓	✓	✓	✓	✓	✓	OK	
17	17	Canteen Ground Floor	✓	✓	✓	✓	✓	✓	OK	
18	18	Canteen First Floor	✓	✓	✓	✓	✓	✓	OK	
19	19	Canteen Second Floor	✓	✓	✓	✓	✓	✓	OK	
20	20	Polytechnic Ground Fir.	✓	✓	✓	✓	✓	✓	OK	

Not signed by J.B. (Signature)

वरिष्ठ यंत्रणे काम करायान झालेले आहे.

~~Signature~~ Bhundekar (Sukal S. U.) MSUPONISAR



Jan - 2015

HYDRANT VALVE'S REPORT									
Sr.No.	H.Y.D. No	Area	Spares					Oiling & Greasing	Remark
			LUG	OUTER WASHER	Spindle Washer	Operating Wheel	Spindel		
21	21	Polytechnic First Floor	✓	✓	✓	✓	✓	✓	OK
22	22	Polytechnic Second Floor	✓	✓	✓	✓	✓	✓	OK
23	23	Polytechnic Third Floor	✓	✓	✓	✓	✓	✓	OK
24	24	Polytechnic Fourth Floor	✓	✓	✓	✓	✓	✓	OK
25	25	Polytechnic Fifth Floor	✓	✓	✓	✓	✓	✓	OK
26	26	Institute Ground Floor	✓	✓	✓	✓	✓	✓	OK
27	27	Institute First Floor	✓	✓	✓	✓	✓	✓	OK
28	28	Institute Second Floor	✓	✓	✓	✓	✓	✓	OK
29	29	Institute Third Floor	✓	✓	✓	✓	✓	✓	OK
30	30	Institute Fourth Floor	✓	✓	✓	✓	✓	✓	OK
31	31	Institute Fifth Floor	✓	✓	✓	✓	✓	✓	OK
32	32	New W/S Ground Floor	✓	✓	✓	✓	✓	✓	OK
33	33	New W/S First Floor	✓	✓	✓	✓	✓	✓	OK
34	34	New W/S Second Floor	✓	✓	Change	✓	✓	✓	OK
35	35	New W/S Third Floor	✓	✓	✓	✓	✓	✓	OK
36	36	New W/S Fourth Floor	✓	✓	Change	✓	✓	✓	OK
37	37	New W/S Fifth Floor	✓	✓	Change	✓	✓	✓	OK

वरिष्ठ प्रयोगे काम उद्योग आलेले आहे.

[Signature]
M. R.

[Signature]
M. SUPERVISOR

[Signature]
Incharge



Jan-2015

Jan-2015

Fire pump house report						
No	Type	Rubber Sheet	Dish Washer	Gasket Fitting		Remark
1	Non Return Valve (Jockey)	√	√	√		OK
2	Non Return Valve (Main)	√	√	√		OK
3	Non Return Valve (Spare)					OK
		Auto	Setting	Cable	Electrical Switch	
1	Pressure Guage (Jockey)	√	Start-5Kg, Stop-7Kg	√	√	OK
2	Pressure Guage (Main)	√	Start-4Kg, Stop-Manu	√	√	OK
3	Pressure Guage (Spare)	√	Start-3Kg, Stop-Manu	√	√	OK
		Guage	Syphon	Valve		
1	Pressure Guage (Jockey)	√	√	√		OK
2	Pressure Guage (Main)	√	√	√		OK
3	Pressure Guage (Spare)	√	√	√		OK

वर्षिक प्रयोग काम करवात आलेले आहे.

Bhandekar
(Sulim S. K.)
M. Supervisor

~~Signature~~
Khandekar S.V.



~~Signature~~
(Sulim S. K.)

Jan - 2015

Fire Hose Reel Report

HR No	Area	Nozzle	Rubber pipe	Hose clamp	Oiling greasing	Remark
1	Canteen Ground Floor	Change	√	√	√	OK
2	Canteen First Floor	√	√	√	√	OK
3	Canteen Second Floor	√	√	√	√	OK
4	Polytechnic Ground Flr.	√	√	√	√	OK
5	Polytechnic First Floor	√	√	√	√	OK
6	Polytechnic Second Floor	√	√	√	√	OK
7	Polytechnic Third Floor	√	√	√	√	OK
8	Polytechnic Fourth Floor	√	√	√	√	OK
9	Polytechnic Fifth Floor	√	√	√	√	OK
10	Institute Ground Floor Eno.	√	√	√	√	Hose clip fitting OK
11	Institute First Floor -11-	√	√	√	√	OK
12	Institute Second Floor -11-	√	√	√	√	OK
13	Institute Third Floor -11-	√	√	√	√	OK
14	Institute Fourth Floor -11-	√	√	√	√	OK
15	Institute Fifth Floor -11-	√	√	√	√	OK
16	New W/S Ground Floor	√	√	√	√	OK
17	New W/S First Floor	√	√	√	√	Ball valve change OK
18	New W/S Second Floor	√	√	√	√	OK
19	New W/S Third Floor	√	√	√	√	OK
20	New W/S Fourth Floor	√	√	√	√	OK
21	New W/S Fifth Floor	Change	√	√	√	

(Signature)
(Name P)

वरिष्ठ प्रशासक एवं इलेक्ट्रिकल अधिकारी
Ghundeley
(1010/141-142)

(Signature)
S.V.

(Signature)

HOSE BOX REPORT

Jan - 2015

HOSE BOX REPORT									
Sr No	Hose Box No	Area	Door Condition	Lock Key	No. of Hoses	No. of Branch Pipe	Servicing Date:-		Remark
							No. of Washer	Glass	
17	17	Canteen Ground Floor	√	√	2	1	√	√	OK
18	18	Canteen First Floor	√	√	2	1	√	√	OK
19	19	Canteen Second Floor	√	√	2	1	√	√	OK
20	20	Polytechnic Ground Fir.	√	√	2	1	√	√	OK
21	21	Polytechnic First Floor	√	√	2	1	√	√	OK
22	22	Polytechnic Second Floor	√	√	2	1	√	Change	Door glass fitted OK
23	23	Polytechnic Third Floor	√	√	2	1	Change	√	Hose pipe winding OK
24	24	Polytechnic Fourth Floor	√	√	2	1	√	√	New hose female coupling fitted OK
25	25	Polytechnic Fifth Floor	√	√	2	1	√	√	OK
26	26	Institute Ground Floor	√	√	2	1	√	Change	OK
27	27	Institute First Floor	√	Change	2	1	Change	Change	OK
28	28	Institute Second Floor	√	Change	2	1	Change	√	OK
29	29	Institute Third Floor	√	√	2	1	Change	√	OK
30	30	Institute Fourth Floor	√	√	2	1	√	√	OK
31	31	Institute Fifth Floor	√	√	2	1	√	√	OK
32	32	New W/S Ground Floor	√	√	2	1	√	√	OK
33	33	New W/S First Floor	√	√	2	1	√	√	OK
34	34	New W/S Second Floor	√	√	2	1	√	√	OK
35	35	New W/S Third Floor	√	√	2	1	√	√	OK
36	36	New W/S Fourth Floor	√	√	2	1	√	√	OK
37	37	New W/S Fifth Floor	√	√	2	1	√	√	OK

वरिष्ठ प्रमाणे काम कुशलता मालेले आहे.

(Signature)
(Name P.)

(Signature)
S. Handekar
(S. W. S. U.)
M. SUPERVISOR

(Signature)
K. S. Kulkarni
S. V.

(Signature)

HOSE BOX REPORT

Jan-2015

HOSE BOX REPORT									
Sr No	Hose Box No	Area	Door Condition	Lock Key	No. of Hoses	No. of Branch Pipe	Servicing Data:-		Remark
							No. of Washer	Glass	
1	1	Near pump House	√	√	2	1	√	Change	Hose pipe winding OK 02 NCS
2	2	Pharmacy Back Side	√	√	2	1	√	√	OK
3	3	Near Canteen	√	√	2	1	√	√	OK
4	4	Back Side Canteen	√	Change	2	1	√	√	OK
5	5	Near Canteen Lawns	√	Change	2	1	√	Change	OK
6	6	Back Side Polytechnic	√	√	2	1	√	Change	OK
7	7	Back Side New W. Shop	√	√	2	1	√	√	OK
8	8	Near Workshop	√	Change	2	1	√	Change	Hose box bottom air broken
9	9	Near Workshop	√	√	2	1	Change	√	OK
10	10	Near Workshop	√	Change	2	1	√	Change	OK
11	11	Back Side Institute	√	Change	2	1	√	Change	OK
12	12	Back Side Institute	√	Change	2	1	√	Change	OK
13	13	Front Off Core Building	√	√	2	1	√	√	OK
14	14	Front Off Core Building	√	√	2	1	√	Change	OK
15	15	Back Side Sec. Gate-1	√	Change	2	1	√	Change	OK
16	16	Back Side Sec. Gate-1	√	Change	2	1	√	Change	OK

वरिष्ठ प्रमाणे काम उच्चगतिमा मालिके कोषि

(Signature)
(Name P.)

Bhandevar
(Supt. S. U.)
M. SUPERVISOR

(Signature)
ELECTRICIAN

(Signature)

the pump house report

No	HP	Love joy coupling	Rubber spider	Gland packing	Greasing	Alignment	Electrical	Remark
1	Jockey	Change	✓	✓	✓	✓	✓	OK
2	Main	✓	✓	✓	✓	✓	✓	OK
3	Spare	✓	✓	✓	✓	✓	✓	OK
								OK
								OK
No	Valve Type	Handle	Gland packing	Spindle	Gasket	Greasing		Remark
1	Sluice Valve (Jockey)	✓	✓	✓	✓	✓		OK
2	Sluice Valve (Main)	✓	✓	✓	✓	✓		OK
3	Sluice Valve (Spare)	✓	✓	✓	✓	✓		OK
4	B.F Valve (Jockey)	✓	✓	✓	✓	✓		OK
5	B.F Valve (Main)	✓	✓	✓	✓	✓		OK
6	B.F Valve (Spare)	✓	✓	✓	✓	✓		OK
7	B.F Valve (Water inlet tank)	✓	✓	✓	✓	✓		OK
Outside Area Sluice & B.F Valves								
No	Valve Type	Handle	Gland Packing	Spindle	Gasket	Greasing	Remark	Area
1	Sluice Valve	✓	✓	✓	✓	✓	OK	Near fire pump house
2	Sluice Valve	✓	✓	✓	✓	✓	OK	Near fire pump house
3	Sluice Valve	✓	✓	✓	✓	✓	OK	Back side pharmacy
4	Sluice Valve	✓	✓	✓	✓	✓	OK	Near Workshop
5	Sluice Valve	✓	✓	✓	✓	✓	OK	Back side institute
6	B.F Valve	✓	✓	✓	✓	✓	OK	Canteen riser
7	B.F Valve	✓	✓	✓	✓	✓	OK	Polytechnic riser
8	B.F Valve	✓	✓	✓	✓	✓	OK	Institute riser
9	B.F Valve	✓	✓	✓	✓	✓	OK	New workshop riser

(Signature)
(Name P.)

Handwritten notes in Malayalam script, including "Handwritten (Initials 54)" and other illegible text.

(Signature)
Handwritten signature and text.

(Signature)
Handwritten signature.